

SCHOOL LEAD MONITORING RESULTS

<u>SAMPLE ID</u>	<u>SCHOOL & SAMPLE LOCATION</u>	<u>DATE COLLECTED</u>	<u>LEAD mg/L</u>	<u>Date Analyzed</u> <u>Lead</u>
1608299	#1 Kitchen Sink	9/22/2016	0.016	10/6/16
1608300	#2 Kitchen Bath	9/22/2016	0.0042	10/6/16
1608301	#3 Kitchen Small Slnk	9/22/2016	0.0024	10/6/16
1608302	#4 Kitchen Eye Wash	9/22/2016	0.014	10/6/16
1608303	#5 Nurse Sink	9/22/2016	0.007	10/6/16
1608304	#6 Nurse Back Sink	9/22/2016	0.0058	10/6/16
1608305	#7 Nurse Bathroom	9/22/2016	0.0059	10/6/16
1608306	#8 Principals Bathoomr	9/22/2016	0.012	10/6/16
1608307	#9 Aides Sink	9/22/2016	0.022	10/6/16
1608308	#10 Office area Womens Sink	9/22/2016	0.003	10/6/16
1608309	#11 Office Area Mens	9/22/2016	0.0057	10/6/16
1608310	#12 Office Area Fountain	9/22/2016	0.0026	10/6/16
1608311	#13 94-Sink	9/22/2016	0.0042	10/6/16
1608312	#14 94 Bathroom	9/22/2016	0.0052	10/6/16
1608313	#15 93 Sink	9/22/2016	0.0031	10/6/16
1608314	#16 93 Bathroom	9/22/2016	0.0048	10/6/16
1608315	#17 92 Sink	9/22/2016	0.0025	10/6/16
1608316	#18 91 Bath	9/22/2016	0.0044	10/6/16
1608317	#19 91 Sink	9/22/2016	0.0036	10/6/16
1608318	#20 89 Fountain	9/22/2016	0.0046	10/6/16
1608319	#21 86 Fountain	9/22/2016	0.014	10/6/16
1608320	#22 Faucet Tara	9/22/2016	0.0049	10/6/16
1608321	#23 84 Fountain	9/22/2016	0.0069	10/6/16
1608322	#24 85 Faucet	9/22/2016	0.0037	10/6/16
1608323	#25 82 Fountain	9/22/2016	0.0055	10/6/16
1608324	#26 83 Faucet	9/22/2016	0.0072	10/6/16
1608325	#27 80 Fountain	9/22/2016	0.0051	10/6/16
1608326	#28 79 Slnk	9/22/2016	0.0036	10/6/16
1608327	#29 Library office	9/22/2016	0.0036	10/6/16
1608328	#30 3-4 Drinking fountain	9/22/2016	0.0016	10/6/16

SCHOOL LEAD MONITORING RESULTS

<u>SAMPLE ID</u>	<u>SCHOOL & SAMPLE LOCATION</u>	<u>DATE COLLECTED</u>	<u>LEAD mg/L</u>	<u>Date Analyzed</u> <u>Lead</u>
1608329	#31 3-4 Boys	9/22/2016	<0.001	10/6/16
1608330	#32 3-4 Girls	9/22/2016	0.0032	10/6/16
1608331	#33 3-4 Girls Sinkl	9/22/2016	0.0024	10/6/16
1608332	#34 74 Fountain	9/22/2016	0.0048	10/6/16
1608333	#35 1-2 Womens	9/22/2016	0.0048	10/6/16
1608334	#36 1-2 Mens	9/22/2016	0.01	10/6/16
1608335	#37 64 Fountain	9/22/2016	0.0053	10/6/16
1608336	#38 67 Fountain	9/22/2016	0.0095	10/6/16
1608337	#39 66 Fountain	9/22/2016	0.0087	10/6/16
1608338	#40 75 Fountain Boucher	9/22/2016	0.002	10/6/16
1608339	#41 73 Fountain James	9/22/2016	0.0044	10/6/16
1608340	#42 68 Fountain	9/22/2016	0.0061	10/6/16
1608341	#4370 Fountain	9/22/2016	0.0023	10/6/16
1608342	#44 71 Fountain	9/22/2016	0.0031	10/6/16
1608343	#45 69 Fountain	9/22/2016	0.0059	10/6/16
1608344	#46 51 Womens Bath	9/22/2016	0.008	10/6/16
1608345	#47 52 Mens Bath	9/22/2016	0.013	10/6/16
1608346	#48 Gym Drinking Fountain	9/22/2016	<0.001	10/6/16
1608347	#49 Girls Locker Room	9/22/2016	0.0094	10/6/16
1608348	#50 Boys Locker Room	9/22/2016	0.013	10/6/16
1608349	#51 48 Fountain	9/22/2016	0.0023	10/6/16
1608350	#52 50 Fountain	9/22/2016	0.0074	10/6/16
1608351	#53 49 Fountain	9/22/2016	0.023	10/6/16
1608352	#54 46 Fountain	9/22/2016	0.0045	10/6/16
1608353	#55 47 Fountain	9/22/2016	0.035	10/6/16
1608354	#56 Art Room	9/22/2016	0.0013	10/6/16
1608355	#57 45 Fountain	9/22/2016	0.029	10/6/16
1608356	#58 43 Staff Room	9/22/2016	0.02	10/6/16
1608357	#59 41 Fountain	9/22/2016	0.025	10/6/16
1608358	#60 Faculty Womens Bath	9/22/2016	0.021	10/6/16

SCHOOL LEAD MONITORING RESULTS

<u>SAMPLE ID</u>	<u>SCHOOL & SAMPLE LOCATION</u>	<u>DATE COLLECTED</u>	<u>LEAD mg/L</u>	<u>Date Analyzed</u> <u>Lead</u>
1608359	#61 Custodial Slop Sink Cafeteria	9/22/2016	0.0012	10/6/16
1608360	#62 Cafeteria Drinking Fountain	9/22/2016	0.011	10/6/16
1608361	#63 31 Sink	9/22/2016	0.0042	10/6/16
1608362	#64 30 Slnk	9/22/2016	0.03	10/6/16
1608363	#65 16 Fountain	9/22/2016	0.019	10/6/16
1608364	#66 28 Fountain	9/22/2016	0.0052	10/6/16
1608365	#67 17 Fountain	9/22/2016	0.013	10/6/16
1608366	#68 27 Fountain	9/22/2016	0.0036	10/6/16
1608367	#69 18 Fountain	9/22/2016	0.009	10/6/16
1608368	#70 20 Fountain	9/22/2016	0.013	10/6/16
1608369	#71 5-6 Drinking	9/22/2016	0.0014	10/6/16
1608370	#72 21 Sink	9/22/2016	0.085	10/6/16
1608371	#73 5-6 Boys Sink	9/22/2016	0.0076	10/6/16
1608372	#74 5-6 Girls Sink	9/22/2016	0.0023	10/6/16
1608373	#75 22 Fountain	9/22/2016	0.038	10/6/16
1608374	#76 24 Fountain	9/22/2016	0.0052	10/6/16
1608375	#77 29 Sink Lizzio	9/22/2016	0.0025	10/6/16
1608376	#78 23 Fountain	9/22/2016	0.0043	10/6/16
1608377	#79 29 Bathroom Lizzio	9/22/2016	0.0037	10/6/16
1608378	#80 29 A Fountain	9/22/2016	0.0036	10/6/16
1608379	#81 29 A	9/22/2016	0.0029	10/6/16
1608380	#82 Megans Slop Slnk	9/22/2016	0.027	10/6/16
1608381	#83 Outside Drinking Fountain	9/22/2016	0.0075	10/6/16
1608382	#84 Sink Bus Bay Garage	9/22/2016	0.0022	10/6/16
1608383	#85 Ladies bathroom sink #1	9/22/2016	0.028	10/6/16
1608384	#86 Ladies bathroom sink #2	9/22/2016	0.012	10/6/16
1608385	#87 Fountain Bus Garage New	9/22/2016	0.0069	10/6/16
1608386	#88 Sink in Break room new bus Garage	9/22/2016	0.006	10/6/16
1608387	#89 Mens bathroom sink new garage #1	9/22/2016	0.025	10/6/16
1608388	#90 Mens bathroom sink new garage #2	9/22/2016	0.028	10/6/16

JH CONSULTING, GROUP, INC
PO BOX 705
NEWTONVILLE, NY 12128
(518) 785-9839

SCHOOL LEAD MONITORING RESULTS

<u>SAMPLE ID</u>	<u>SCHOOL & SAMPLE LOCATION</u>	<u>DATE COLLECTED</u>	<u>LEAD mg/L</u>	<u>Date Analyzed</u> <u>Lead</u>
1608389	#91 Sink in concession stand on field	9/22/2016	0.011	10/6/16
1608390	#92 Sink in bathroom old bus garage	9/22/2016	0.024	10/6/16
1608391	#93 Slop sink in new bus garage	9/22/2016	0.0046	10/6/16
1608392	#94 92 Bathroom	9/22/2016	0.0056	10/6/16