

SCHOOL LEAD MONITORING RESULTS

| SAMPLE ID | <u>SCHOOL & SAMPLE LOCATION</u> | DATE COLLECTED | <u>LEAD mg/L</u> | <u>Date Analyzed</u> <u>Lead</u> |
|------------------|--|-----------------------|-------------------------|---|
| 1608299 | #1 Kitchen Sink | 9/22/2016 | 0.016 | 10/6/16 |
| 1608300 | #2 Kitchen Bath | 9/22/2016 | 0.0042 | 10/6/16 |
| 1608301 | #3 Kitchen Small Slnk | 9/22/2016 | 0.0024 | 10/6/16 |
| 1608302 | #4 Kitchen Eye Wash | 9/22/2016 | 0.014 | 10/6/16 |
| 1608303 | #5 Nurse Sink | 9/22/2016 | 0.007 | 10/6/16 |
| 1608304 | #6 Nurse Back Sink | 9/22/2016 | 0.0058 | 10/6/16 |
| 1608305 | #7 Nurse Bathroom | 9/22/2016 | 0.0059 | 10/6/16 |
| 1608306 | #8 Principals Bathroomr | 9/22/2016 | 0.012 | 10/6/16 |
| 1608307 | #9 Aides Sink | 9/22/2016 | 0.022 | 10/6/16 |
| 1608308 | #10 Office area Womens Sink | 9/22/2016 | 0.003 | 10/6/16 |
| 1608309 | #11 Office Area Mens | 9/22/2016 | 0.0057 | 10/6/16 |
| 1608310 | #12 Office Area Fountain | 9/22/2016 | 0.0026 | 10/6/16 |
| 1608311 | #13 94-Sink | 9/22/2016 | 0.0042 | 10/6/16 |
| 1608312 | #14 94 Bathroom | 9/22/2016 | 0.0052 | 10/6/16 |
| 1608313 | #15 93 Sink | 9/22/2016 | 0.0031 | 10/6/16 |
| 1608314 | #16 93 Bathroom | 9/22/2016 | 0.0048 | 10/6/16 |
| 1608315 | #17 92 Sink | 9/22/2016 | 0.0025 | 10/6/16 |
| 1608316 | #18 91 Bath | 9/22/2016 | 0.0044 | 10/6/16 |
| 1608317 | #19 91 Sink | 9/22/2016 | 0.0036 | 10/6/16 |
| 1608318 | #20 89 Fountain | 9/22/2016 | 0.0046 | 10/6/16 |
| 1608319 | #21 86 Fountain | 9/22/2016 | 0.014 | 10/6/16 |
| 1608320 | #22 Faucet Tara | 9/22/2016 | 0.0049 | 10/6/16 |
| 1608321 | #23 84 Fountain | 9/22/2016 | 0.0069 | 10/6/16 |
| 1608322 | #24 85 Faucet | 9/22/2016 | 0.0037 | 10/6/16 |
| 1608323 | #25 82 Fountain | 9/22/2016 | 0.0055 | 10/6/16 |
| 1608324 | #26 83 Faucet | 9/22/2016 | 0.0072 | 10/6/16 |
| 1608325 | #27 80 Fountain | 9/22/2016 | 0.0051 | 10/6/16 |
| 1608326 | #28 79 Slnk | 9/22/2016 | 0.0036 | 10/6/16 |
| 1608327 | #29 Library office | 9/22/2016 | 0.0036 | 10/6/16 |
| 1608328 | #30 3-4 Drinking fountain | 9/22/2016 | 0.0016 | 10/6/16 |

SCHOOL LEAD MONITORING RESULTS

| SAMPLE ID | <u>SCHOOL & SAMPLE LOCATION</u> | DATE COLLECTED | <u>LEAD mg/L</u> | <u>Date Analyzed</u> <u>Lead</u> |
|------------------|--|-----------------------|-------------------------|---|
| 1608329 | #31 3-4 Boys | 9/22/2016 | <0.001 | 10/6/16 |
| 1608330 | #32 3-4 Girls | 9/22/2016 | 0.0032 | 10/6/16 |
| 1608331 | #33 3-4 Girls Sinkl | 9/22/2016 | 0.0024 | 10/6/16 |
| 1608332 | #34 74 Fountain | 9/22/2016 | 0.0048 | 10/6/16 |
| 1608333 | #35 1-2 Womens | 9/22/2016 | 0.0048 | 10/6/16 |
| 1608334 | #36 1-2 Mens | 9/22/2016 | 0.01 | 10/6/16 |
| 1608335 | #37 64 Fountain | 9/22/2016 | 0.0053 | 10/6/16 |
| 1608336 | #38 67 Fountain | 9/22/2016 | 0.0095 | 10/6/16 |
| 1608337 | #39 66 Fountain | 9/22/2016 | 0.0087 | 10/6/16 |
| 1608338 | #40 75 Fountain Boucher | 9/22/2016 | 0.002 | 10/6/16 |
| 1608339 | #41 73 Fountain James | 9/22/2016 | 0.0044 | 10/6/16 |
| 1608340 | #42 68 Fountain | 9/22/2016 | 0.0061 | 10/6/16 |
| 1608341 | #4370 Fountain | 9/22/2016 | 0.0023 | 10/6/16 |
| 1608342 | #44 71 Fountain | 9/22/2016 | 0.0031 | 10/6/16 |
| 1608343 | #45 69 Fountain | 9/22/2016 | 0.0059 | 10/6/16 |
| 1608344 | #46 51 Womens Bath | 9/22/2016 | 0.008 | 10/6/16 |
| 1608345 | #47 52 Mens Bath | 9/22/2016 | 0.013 | 10/6/16 |
| 1608346 | #48 Gym Drinking Fountain | 9/22/2016 | <0.001 | 10/6/16 |
| 1608347 | #49 Girls Locker Room | 9/22/2016 | 0.0094 | 10/6/16 |
| 1608348 | #50 Boys Locker Room | 9/22/2016 | 0.013 | 10/6/16 |
| 1608349 | #51 48 Fountain | 9/22/2016 | 0.0023 | 10/6/16 |
| 1608350 | #52 50 Fountain | 9/22/2016 | 0.0074 | 10/6/16 |
| 1608351 | #53 49 Fountain | 9/22/2016 | 0.023 | 10/6/16 |
| 1608352 | #54 46 Fountain | 9/22/2016 | 0.0045 | 10/6/16 |
| 1608353 | #55 47 Fountain | 9/22/2016 | 0.035 | 10/6/16 |
| 1608354 | #56 Art Room | 9/22/2016 | 0.0013 | 10/6/16 |
| 1608355 | #57 45 Fountain | 9/22/2016 | 0.029 | 10/6/16 |
| 1608356 | #58 43 Staff Room | 9/22/2016 | 0.02 | 10/6/16 |
| 1608357 | #59 41 Fountain | 9/22/2016 | 0.025 | 10/6/16 |
| 1608358 | #60 Faculty Womens Bath | 9/22/2016 | 0.021 | 10/6/16 |

SCHOOL LEAD MONITORING RESULTS

| SAMPLE ID | <u>SCHOOL & SAMPLE LOCATION</u> | <u>DATE COLLECTED</u> | <u>LEAD mg/L</u> | <u>Date Analyzed</u> <u>Lead</u> |
|------------------|--|------------------------------|-------------------------|---|
| 1608359 | #61 Custodial Slop Sink Cafeteria | 9/22/2016 | 0.0012 | 10/6/16 |
| 1608360 | #62 Cafeteria Drinking Fountain | 9/22/2016 | 0.011 | 10/6/16 |
| 1608361 | #63 31 Sink | 9/22/2016 | 0.0042 | 10/6/16 |
| 1608362 | #64 30 Slnk | 9/22/2016 | 0.03 | 10/6/16 |
| 1608363 | #65 16 Fountain | 9/22/2016 | 0.019 | 10/6/16 |
| 1608364 | #66 28 Fountain | 9/22/2016 | 0.0052 | 10/6/16 |
| 1608365 | #67 17 Fountain | 9/22/2016 | 0.013 | 10/6/16 |
| 1608366 | #68 27 Fountain | 9/22/2016 | 0.0036 | 10/6/16 |
| 1608367 | #69 18 Fountain | 9/22/2016 | 0.009 | 10/6/16 |
| 1608368 | #70 20 Fountain | 9/22/2016 | 0.013 | 10/6/16 |
| 1608369 | #71 5-6 Drinking | 9/22/2016 | 0.0014 | 10/6/16 |
| 1608370 | #72 21 Sink | 9/22/2016 | 0.085 | 10/6/16 |
| 1608371 | #73 5-6 Boys Sink | 9/22/2016 | 0.0076 | 10/6/16 |
| 1608372 | #74 5-6 Girls Sink | 9/22/2016 | 0.0023 | 10/6/16 |
| 1608373 | #75 22 Fountain | 9/22/2016 | 0.038 | 10/6/16 |
| 1608374 | #76 24 Fountain | 9/22/2016 | 0.0052 | 10/6/16 |
| 1608375 | #77 29 Sink Lizzio | 9/22/2016 | 0.0025 | 10/6/16 |
| 1608376 | #78 23 Fountain | 9/22/2016 | 0.0043 | 10/6/16 |
| 1608377 | #79 29 Bathroom Lizzio | 9/22/2016 | 0.0037 | 10/6/16 |
| 1608378 | #80 29 A Fountain | 9/22/2016 | 0.0036 | 10/6/16 |
| 1608379 | #81 29 A | 9/22/2016 | 0.0029 | 10/6/16 |
| 1608380 | #82 Megans Slop Slnk | 9/22/2016 | 0.027 | 10/6/16 |
| 1608381 | #83 Outside Drinking Fountain | 9/22/2016 | 0.0075 | 10/6/16 |
| 1608382 | #84 Sink Bus Bay Garage | 9/22/2016 | 0.0022 | 10/6/16 |
| 1608383 | #85 Ladies bathroom sink #1 | 9/22/2016 | 0.028 | 10/6/16 |
| 1608384 | #86 Ladies bathroom sink #2 | 9/22/2016 | 0.012 | 10/6/16 |
| 1608385 | #87 Fountain Bus Garage New | 9/22/2016 | 0.0069 | 10/6/16 |
| 1608386 | #88 Sink in Break room new bus Garage | 9/22/2016 | 0.006 | 10/6/16 |
| 1608387 | #89 Mens bathroom sink new garage #1 | 9/22/2016 | 0.025 | 10/6/16 |
| 1608388 | #90 Mens bathroom sink new garage #2 | 9/22/2016 | 0.028 | 10/6/16 |

JH CONSULTING, GROUP, INC
PO BOX 705
NEWTONVILLE, NY 12128
(518) 785-9839

SCHOOL LEAD MONITORING RESULTS

| SAMPLE ID | <u>SCHOOL & SAMPLE LOCATION</u> | DATE COLLECTED | <u>LEAD mg/L</u> | <u>Date Analyzed</u> <u>Lead</u> |
|------------------|--|-----------------------|-------------------------|---|
| 1608389 | #91 Sink in concession stand on field | 9/22/2016 | 0.011 | 10/6/16 |
| 1608390 | #92 Sink in bathroom old bus garage | 9/22/2016 | 0.024 | 10/6/16 |
| 1608391 | #93 Slop sink in new bus garage | 9/22/2016 | 0.0046 | 10/6/16 |
| 1608392 | #94 92 Bathroom | 9/22/2016 | 0.0056 | 10/6/16 |